

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Amini Oil Corporation		8. Farm or Lease Name Hutcherson
3. Address of Operator 400 Wall Towers West Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>9-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Vada
15. Elevation (Show whether DF, RT, GR, etc.) 4242 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

12-14-71 Moved in csg. pulling unit.
12-15-71 Run 87 jts 2 3/8" tbg - screw on tbg. Run shot @ 6300'. Pulled 130 jts tbg.
12-16-71 Pulled 80 jts tbg. Weld on 5 1/2" nipple. Spotted 30 sk plug @ 9800' & filled hole w/mud.
12-17-71 Shot csg. @ 5500'. Spotted 25 sk plug @ 5500'. Pulled 15' 5 1/2" csg.
12-18-71 Worked csg.
12-20-71 Pulled 101 jts. 5 1/2" csg.
12-21-71 Spotted 25 sk plug @ 5350'. Pulled 41 jts 5 1/2" csg. Spotted 50 sk plug @ 3950'. Weld on 8 5/8" pull nipple.
12-22-71 Shot csg. @ 1400'. Shot again @ 950'. Pulled 95' 8 5/8" csg. Spotted 25 sk plug @ 950'. Spotted 25 sk plug @ 363'. Set 10 sk plug in top of surface csg. & installed marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Karin Godwin TITLE Agent DATE 2-25-72
APPROVED BY John W. Runyan TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: