

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22465
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name MOUNSEY
8. Well No. 1
9. Pool name or Wildcat VADA-PENN
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4231.5 RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator M & G OIL, INC.
3. Address of Operator P.O. BOX 957, CROSSROAD, NM 88114

4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>14</u> Township <u>9S</u> Range <u>34E</u> NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- | | | | | | | |
|-----|------|----|---|---------------|------|----------|
| (1) | PLUG | 35 | SX ON TOP OF 5-1/2" CIBP @ 9700' | ESTIMATED TOC | 9384 | 12-21-92 |
| (2) | PLUG | 25 | SX INSIDE 5-1/2 2 6200' | ESTIMATED TOC | 5884 | 12-21-92 |
| (3) | PLUG | 60 | SX PLUG @ 4130 50' IN 50' OUT (5-1/2" STUB) (8-5/8" SHOE) | | | |
| | | | WOC TAG PLUG @ 3935' | | | 12-21-92 |
| (4) | PLUG | 90 | SX PLUG @ 470' (8-5/8 STUB AND 13-3/8 SHOE) | | | |
| | | | WOC TAG PLUG @ 290' | | | 12-23-92 |
| (5) | PLUG | 20 | SX PLUG @ 30' CIRC TO SURF. INSTALL DRY HOLE MARKER | | | 12-28-92 |
| | | | JOB COMPLETE | | | |

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE JOEY FIELDS TITLE OPERATIONS MANAGER DATE JANUARY 11, 199
TYPE OR PRINT NAME JOEY FIELDS TELEPHONE NO. (915) 683-97

(This space for State Use)

APPROVED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____
CONDITIONS OF APPROVAL, IF ANY: