

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-22465
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Mounsey
8. Well No. 1
9. Pool name or Wildcat Vada-Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4231.5 RKB

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator M & G Oil, Inc.	3. Address of Operator P.O. Box 957 Crossroads, NM 88114	4. Well Location Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line Section 14 Township 9S Range 34E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4231.5 RKB			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) CIBP +35 sx. 9700'
- (2) Load hole w/10# brine w/25# SWG per barrel
- (3) 100' plug @ 6200' inside 5½" csg. or 50'in-50' out on 5½" stub plug
- (4) 100' plug 50' in-50' out 5½" stub plug if csg. not cut @ 6200'
- (5) 100' 8-5/8" shoe plug 4066'-3966' ***TAG***
- (6) 100' plug 50' in 50' out 8-5/8" stub plug
- (7) 100' 13-3/8" shoe plug 414-314'
- (8) 20 sx. surface plug w/dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Frelan Fields* TITLE Agent DATE 12/7/92
(915)
TYPE OR PRINT NAME Frelan Fields TELEPHONE NO. 366-1852

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DEC 07 1992

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: