

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Southland Royalty Company	8. Form or Lease Name Epperson
3. Address of Operator 1405 Wilco Bldg., Midland, Texas	9. Well No. 4
4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>11-South</u> RANGE <u>33-East</u> NMPM.	10. Field and Pool, or Wildcat Inbe (Permo-Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4226.0' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

plug and aband by Bonanza Casing Pulling Co., Hobbs, New Mexico.
Approximate date to start 11-21-75.

Propose to do the following work:

1. Set 35' plug @ 9800'. (IF USED w/ B.P. - 100' PLUG REQ w/OUT B.P.)
2. 25sk plug @ 5½" stub approximately 4500'.
3. 50sx in and out of 8 5/8" shoe @ 4000'.
4. 35sx @ 8 5/8" stub approximately 1100'.
5. 35sx in and out of 11 3/4" @ 390'. 100' PLUG REQ
6. 10sx plug @ surface.
7. Clean location and install well marker.

MUD REQ IN THE HOLE FROM 1ST STUB

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE VALID.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C.H. Can</u>	TITLE <u>Dist. Production Supt.</u>	DATE <u>10-29-75</u>
APPROVED BY <u>Jerry S. Lyster</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>OCT 1 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		