

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 29 11 32 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
----------------------------	---	------------------------------

5. State Oil & Gas Lease No.
"2393"

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Drilling	7. Unit Agreement Name
2. Name of Operator Jake L. Hamon	8. Farm or Lease Name State "2393"
3. Address of Operator P. O. Box 663, Dallas, Texas 75221	9. Well No. 1
4. Location of Well UNIT LETTER L, 1650 FEET FROM THE South LINE AND 660' FEET FROM THE West LINE, SECTION 5 TOWNSHIP 10-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3974.4 Gr.	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in and rigged up casing pulling rig 8-21-68. Shot off 9-5/8" casing at 1000' and pulled 1000' of 9-5/8" casing out of hole. Ran tubing in hole and set the following plugs through tubing:

- 25 sacks neat cement plug in and out of 9-5/8" casing stub from 970' to 1040'. Set 8-24-68.
- 50 sacks neat cement plug in and out of base of 13-3/8" casing from 355' to 430'. Set 8-24-68.
- 10 sacks neat cement plug in top of 13-3/8" casing. Set 8-24-68.

Installed permanent well marker. Final P & A 8-24-68.

The Commission will be notified when pits are filled and location is cleaned up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Cecil N. Barton</u>	TITLE <u>Pet. Engineer.</u>	DATE <u>August 26, 1968</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Sec. 10294</u>	DATE <u>Aug 28 1968</u>
CONDITIONS OF APPROVAL, IF ANY:		