

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOODS OFFICE D.C.C.
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUN 17 8 23 AM '68

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	K-1112

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Charles B. Read	8. Farm or Lease Name Continental-State
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> , <u>1976.6</u> FEET FROM THE <u>North</u> LINE AND <u>1970.1</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>10S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4197.7' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 117 jts 8-5/8", 32# & 24#, J-55 csg; 4054.01' set @ 4045' RKB;
cmt w/250 sx Incore Poz w/2% gel & 8# salt; 100 sx Incore Neat
w/2% CaCl & 8# salt; plug down @ 11:00 PM 5/14/68. Tested 1500#
for 30 mins., no pressure drop, test OK. WOC 18 hrs.

Ran 9927.15' of 5 1/2", 17# & 15.5#, J-55 & N-80 csg.; set @ 9925' RKB;
cmt. w/500 sx Incor Poz w/2% gel & 8# salt/sx; plug down @ 11:30 AM,
6/10/68. Tested 1500# for 30 mins; no pressure drop; test OK. WOC 18 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles B. Read TITLE Operator DATE June 14, 1968

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: