

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG 2392

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Coquina Oil Corporation	State 36
3. Address of Operator	9. Well No.
418 Building of the Southwest, Midland, Texas 79701	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER J, 2080 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 36 TOWNSHIP 10-S RANGE 33-E NMPM.	Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
GL 4207 KB 4219	Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Conditions:

17 1/2" hole 13 3/8" csg cmtd at 367' w/375 sx - circ.
11" Hole 8 5/8" csg cmtd at 4005' w/500 sx - top cmt ??
7 7/8" Hole 5 1/2" csg cmtd at 9960' w/600 sx - top cmt 7150

PBTD: 9936 Perfs. 9921-9930

Propose to P & A as follows: (1) Spot 25 sx cmt thru tbg inside 5 1/2 casing at 9900'
(2) Cut and pull 5 1/2 csg (3) Spot 25 sx cmt on top of 5 1/2 csg stub (4) 25 sx at top
Glor (5420') (5) Spot 25 sx in bottom of 8 5/8 (6) Spot 25 sx on 8 5/8 stub (7) 25 sx
in bottom 13 3/8" (8) Spot 10 sx in top 13 3/8. Fill hole between plugs with mud.
Erect DHM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. B. Taylor</u>	TITLE <u>Superintendent</u>	DATE <u>5-19-71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT 1</u>	DATE <u>MAY 24 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 21 1971

OIL CONSERVATION CO., INC.
HOBBS, N. M.