

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22577
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-5011
7. Lease Name or Unit Agreement Name Graham "C" State Com
8. Well No. 1
9. Pool name or Wildcat No. Bagley Permo Penn

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Dwight A. Tipton	
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, NM	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>17</u> Township <u>11S</u> Range <u>33E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

CIBP @ 8500 w/250' cement cap  
Load hole w/mud  
25 sx set @ 7000'  
95 sx 50' inside of 4 1/2" stub (4250') - Tagged plug @ 3820'  
55 sx 50' inside of 8 5/8" stub (722') - Tagged plug @ 651'  
75 sx across 11 3/4 shoe (410') - Tagged plug @ 323'  
10 sx surface w/dry hole marker. Well P&A'd 4/1/91  
Location cleaned, leveled and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Holler TITLE Agent DATE 10/7/91  
TYPE OR PRINT NAME Donna Holler TELEPHONE NO. 505-393-2727

(This space for State Use)

APPROVED BY Donna Holler TITLE OIL & GAS DATE 10/7/91  
CONDITIONS OF APPROVAL, IF ANY: