

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No. K-3274</p>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator Sun Oil Company	8. Farm or Lease Name New Mexico "II" State	
3. Address of Operator P. O. Box 1861 Midland, Texas 79701	9. Well No. 1	
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 21 TOWNSHIP 10S RANGE 34E N.M.P.M.	10. Field and Pool, or Wildcat Vada Penn	
15. Elevation (Show whether DF, RT, GR, etc.) KB - 4220		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/24/70 Halliburton spotted 75 sack cement plug 9354-9966 across perfs.
 3/3/70 Shot 5½ casing @ 6500, pull & lay down.
 3/6/70 Run tubing; spot 25 sack plug 6425-6500, 25 sack plug 5432-5505, 100 sack plug 3957-4200. Pressure to 500#.
 3/16/70 Spot 10 sack plug @ surface; install marker.
 4/2/70 Location cleared & all pits levelled.

Casing left in hole:
 370 ft. 13-3/8
 4092 ft. 8-5/8
 3600 ft. 5½

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ruth Hughes</u>	TITLE <u>Proration Clerk</u>	DATE <u>12/23/70</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u>DEC 28 1970</u>
CONDITION OF APPROVAL, IF ANY:		