

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 87240 -

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30 - 025-22582

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

021049

7. Lease Name or Unit Agreement Name:

State 17

7. Well No.

1

8. Pool name or Wildcat

Vada Penn

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Novy Oil & Gas, Inc.

3. Address of Operator

125 N. Market St., Suite 1230, Wichita, KS 67202

4. Well Location

Unit Letter K : 1980 feet from the South line and 1980 feet from the West line

Section 17

Township 10 S

Range 34E

NMPM Lea

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

RKB = 4235

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRU - MOVE IN WORKSTRING

2. SET CIBP @ 9825' - SPOT 35' CEMENT CAP ON TOP

3. CIRC. 9.5# MUD

4. SPOT 35 SXS @ 6915' - 7015'

5. SPOT 45 SXS @ 4125' - 4025' PERF & SQZ. OR PULL 4 1/2 11.6# CASING -TAG

5A. SPOT 40 SXS @ STUB IF CASING PULLED FROM DIFFERENT DEPTH

6. SPOT 35 SXS @ 2000' - 2900' TOP OF SALT

7. SPOT 85 SXS @ 500' - 350' PERF & SQZ. OR PULL 8 5/8 CASING -TAG

7A. SPOT 85 SXS @ STUB IF CASING PULLED FROM DIFFERENT DEPTH

8. SPOT 15 SXS @ SURFACE

9. CUT OFF WELLHEAD & ANCHORS - COVERPIT - INSTALL DRYHOLE MARKER - MOVEOUT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael E. Novy TITLE VICE PRESIDENT DATE 03/21/00

Type or print name Michael E. Novy

Telephone No. 1+(316) 265-4651

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

THE COMMISSION MUST BE NOTIFIED 28