

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>OG 2392</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-1C1) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>MGF Oil Corporation</b>	8. Name of Lease <b>Texas Pacific State</b>
3. Address of Operator <b>1126 Vaughn Building, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>0</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>36</b> TOWNSHIP <b>10-S</b> RANGE <b>33-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Inbe Permo Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4227' KB</b>	12. County <b>Lea</b>

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug in 5 1/2" casing @ 9800', 2 sx cement on top of plug  
Shot 5 1/2" casing off @ 5437'  
Spotted 25 sx in and out of 5 1/2" stub  
Spotted 40 sx in and out of 8 5/8" shoe @ 4040'  
Shot 8 5/8" casing off @ 1054'  
Spotted 40 sx in and out of stub of 8 5/8" casing  
Spotted 25 sx in and out of shoe of 12 3/4" @ 383'  
Spotted 10 sx @ surface

Spotted 10# mud between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>[Signature]</i>	TITLE <b>Engineer</b>	DATE <b>January 12, 1972</b>
APPROVED BY <i>[Signature]</i>	TITLE <b>OIL &amp; GAS INSPECTOR</b>	DATE
CONDITIONS OF APPROVAL, IF ANY:		