

NEW MEXICO OIL CONSERVATION COMMISSION
FIELD TRIP REPORT

✓

Name Jack Griffin Date 10/5/88 Miles 169 District I
Time of Departure 7 AM Time of Return 4 PM Car No. 9169

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Jack Griffin

P O P 4

1 Well - Crossroads Area P & A on:

~~Tatum Housekeeping~~ Drilling GIDP at 472'

H O P 4

10 Wells & Facilities - Crossroads/Tatum Housekeeping
Rapid Co. No cleanup on plugged wells by Baber.

Union Pacific Pits open on drilling well after rig was moved. advised them to fence same.

N. M. Treating Co. Middle Lane Plant No activity.

Mileage

UIC _____
RFA _____
Other 169

Per Diem

UIC _____
RFA _____
Other 6.00

Hours

UIC _____
RFA _____
Other 8

TYPE INSPECTION
PERFORMED

INSPECTION
CLASSIFICATION

NATURE OF SPECIFIC WELL
OR FACILITY INSPECTED

H = Housekeeping
P = Plugging
C = Plugging Cleanup
T = Well Test
R = Repair/Workover
F = Waterflow
M = Mishap or Spill
W = Water Contamination
O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
R = Inspections relating to Reclamation Fund Activity
O = Other - Inspections not related to injection or The Reclamation Fund
E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling
P = Production
I = Injection
C = Combined prod. inj. operations
S = SWD
U = Underground Storage
G = General Operation
F = Facility or location
M = Meeting
O = Other

NEW MEXICO OIL CONSERVATION COMMISSION
FIELD TRIP REPC

INSPECTION	CLASSIFICATION	FACILITY	HOURS	QUARTER HOURS
------------	----------------	----------	-------	---------------

Name Jack Griffin Date 10/4/88 Miles 201 District I
Time of Departure 7 AM Time of Return 4 PM Car No. 9169

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Jack Griffin

P O P 4

1 Well - Crossroads Area P & A on:

~~Renewed - 12-9-34 - Drilled out to 4200 ft. 12-9-34 - plugged and abandoned. bit and scraper run, ready to perforate early Wednesday.~~

M O P 2

1 Facility - Caprock Area Oil Spill:

OXY - St. AD #2 Tank battery 22-10-32 Hole in tank, picked up oil in pasture and hauled saturated dirt to old caliche pit in 2-10-32 on road to No Pit Pete. Location in good shape.

H O P 2

10 Wells -Caprock Area Housekeeping on: OXY and Conoco - all o.k.

Mileage

UIC _____

RFA _____

Other 201

Per Diem

UIC _____

RFA _____

Other 6.00

Hours

UIC _____

RFA _____

Other 8

TYPE INSPECTION
PERFORMED

INSPECTION
CLASSIFICATION

NATURE OF SPECIFIC WELL
OR FACILITY INSPECTED

H = Housekeeping
P = Plugging
C = Plugging Cleanup
T = Well Test
R = Repair/Workover
F = Waterflow
M = Mishap or Spill
W = Water Contamination
O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
R = Inspections relating to Reclamation Fund Activity
O = Other - Inspections not related to injection or The Reclamation Fund
E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling
P = Production
I = Injection
C = Combined prod. inj. operations
S = SWD
U = Underground Storage
G = General Operation
F = Facility or location
M = Meeting
O = Other

INSPECTION	CLASSIFICATION	FACILITY	HOURS	QUARTER HOURS
O	O	O	6	
P	O	P	2	

Signature Jack Bush

1 Well - Crossroads Area P & A on:

[illegible]

Other 8

D = Drilling
P = Production
I = Injection
C = Combined prod. inj.
operations
B = SWD
U = Underground Storage
G = General Operation
F = Facility or location
M = Meeting
O = Other

**NEW MEXICO OIL CONSERVATION" COMMISSION
FIELD TRIP REPO**

I N S P E C T I O N	C L A S S I F I C A T I O N	F A C I L I T Y	H O U R S	Q U A R T E R H O U R S
P	O	P	4	
O	O	P	4	

Name Jack Griffin Date 10/6/88 Miles 295 District I
 Time of Departure 7 AM Time of Return 4 PM Car No. 9169

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Jack Griffin

1 Well - Crossroads Area P & A on:
 Tenneco - Ward Insul #1 D 12-9-34 Plug job complete.

1 Well - Gladiola Area Witness casing inspection log on Gary L. Bennett - Golden Gate #2 F 18-12-38. Atlas Western started tool in hole at approx. 8:30 PM 10/6/88. Tagged plug at approx. 9686'. Logged interval 2 times, I witnessed running of log only. Not qualified to interpret. Finished at approx 10:30 PM 10/6/88. Initialed log and returned 1 Field Print to our office. Witnessed tool run from surface down and back to surface.

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
UIC _____	UIC _____	UIC _____
RFA _____	RFA _____	RFA _____
Other <u>295</u>	Other <u>6.00</u>	Other <u>8</u>

**TYPE INSPECTION
PERFORMED**

**INSPECTION
CLASSIFICATION**

**NATURE OF SPECIFIC WELL
OR FACILITY INSPECTED**

H = Housekeeping
 P = Plugging
 C = Plugging Cleanup
 T = Well Test
 R = Repair/Workover
 F = Waterflow
 M = Mishap or Spill
 W = Water Contamination
 O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
 R = Inspections relating to Reclamation Fund Activity
 O = Other - Inspections not related to injection or The Reclamation Fund

E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling
 P = Production
 I = Injection
 C = Combined prod. inj. operations
 S = SWD
 U = Underground Storage
 G = General Operation
 F = Facility or location
 M = Meeting
 O = Other