

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Com Agr SW-451
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name Ward Insall Com
3. Address of Operator 6800 Park Ten Blvd., San Antonio, Texas 78213	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>9S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4221.3	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. RUPU, NUBOP.
2. Pull rods, tubing and anchor.
3. TIH with bit and scraper and clean out hole to PBTD at 9828'. POOH.
4. Run tubing open ended and spot cement as follows:
 - (a) SPOT 111' of Class "C" cement from 9828' (PBTD) to 9,717' to isolate Bough "C" formation; TAG PLUG
 - (b) Set CIBP at 410'. SPOT 410' of Class "C" cement from 50' below the 13 3/8" casing shoe to the surface.
 - (c) 9.5 ppg salt mud will be left between all plugs.
5. Erect P & A marker to extend at least 4' above ground.
6. RDPU.
7. Clean location and cut off mast anchors.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert A. Mathew TITLE Production Engineering Supervisor DATE March 31, 1982

APPROVED BY Orig. Signed by TITLE Les Clements DATE APR 5 1982
CONDITIONS OF APPROVAL IF ANY
Oil & Gas Insp.

* Set 100' Plug @ 16700' + 4050'

RECEIVED

APR 2 1982

O.C.D.
HOBBS OFFICE