

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.  
NA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name None
2. Name of Operator Sage Energy Company	8. Farm or Lease Name Alice Ann
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>510.5</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>9S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Flying M Bough South
15. Elevation (Show whether DF, RT, GR, etc.) 4350' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug with 35' cement at 8500'±  
Cut 5½" as low as possible and pull 5000'±  
100' plug 1/2 in and 1/2 out of 5½" stub.  
100' at top of San Andres (Top 3451')  
100' at shoe of 8 5/8" 1/2 in and 1/2 out 3467'.  
Cut 8 5/8" 1200'± if possible and pull, if can't pull, must perf. at shoe of 13 3/8"  
and squeeze (100').  
100' at 8 5/8" stub.  
100' at 13 3/8" shoe, 398' shoe.  
10 sxs surface marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Juan Valdez TITLE Production Clerk DATE April 8, 1987

ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY DISTRICT 1 SUPERVISOR TITLE \_\_\_\_\_ DATE APR 15 1987  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 14 1987

OCD  
HOBS OFFICE