

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 2392

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Major, Giebel & Forster	8. Farm or Lease Name T. P. State
3. Address of Operator 1126 Vaughn Building, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER I 660 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 36 TOWNSHIP 10-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4198 GI	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/30/68 Spud well @ 1:00 A.M. Drilled 17 1/2" hole to 369'. Cemented 12 3/4" H-40 34# casing cemented w/350 sx at 369 feet. Cement circulated. Plug down at 10:45 A.M. WOC 13 hrs.

12/1/68 WOC 6 hours Tested casing w/700 psi. OK. Started drilling 11" hole.

12/6/68 Drilled 11" hole to 4000 feet. Cemented 8 5/8" 32 & 24# casing (J-55) at 4000 feet w/400 sx. Plug down at 9:00 A.M. WOC 15 hours.

12/7/68 WOC 3 hours Tested casing w/1500 psi. OK. Started drilling 7 7/8" hole.

18 hrs. minimum WOC time

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>William A. Kerner</u>	TITLE <u>Engineer</u>	DATE <u>December 9, 1968</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>DEC 11 1968</u>
CONDITIONS OF APPROVAL, IF ANY:		