

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG5002 & K2217	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>K.K. Amini</u>		8. Farm or Lease Name <u>Marathon State</u>
3. Address of Operator <u>400 Wall Towers West - Midland, Texas 79701</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>5</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat <u>Vada Penn</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4251 G.L.</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-12-68 Drilled a 7-7/8" hole to T.D. @ 9910'.

9-13-68 Set cement plugs as follows:
 25 sacks @ 9910' (Total Depth) 35 sacks @ 8650'
 25 sacks @ 7770' 25 sacks @ 5460'
 30 sacks @ 4075' (Bottom of 8-5/8" casing @ 4050')

9-14-68 Moved out drilling rig.

9-18-68 Moved in casing pulling rig.

9-19-68 Shot 8-5/8" 24# casing @ 1340'
 Shot 8-5/8" 24# casing @ 1220'

9-20-68 Pulled and layed down 1220' 8-5/8" 24# casing. Ran tubing and set cement plugs as follows:
 25 sacks @ 1250'
 25 sacks @ 390' (Bottom of 12-3/4" casing @ 379')
 10 sacks in top of surface.
 Installed marker and moved out casing pulling rig.

Note: The New Mexico Oil Conservation Commission will be notified when this location is ready to be inspected.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W.D. Frazier</u>	TITLE <u>Engineer</u>	DATE <u>Sept. 27, 1968</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		