

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6802	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - DRY HOLE		7. Unit Agreement Name
2. Name of Operator MONSANTO COMPANY		8. Farm or Lease Name State "L"
3. Address of Operator 101 North Marienfeld, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER P , 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 10-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat Undesignated Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4241' RKB		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled to total depth of 10,020' and plugged and abandoned as follows on 10-26-68: Filled hole w/10# mud, set 25 sx cement plugs at following points: 10,020', 9850', 7750', 5450', 4000'. Shot off 8 5/8" casing @ 1200'. Set 25 sx cement plugs at 1260' & 360'. Set 10 sx cement plug at surface w/4" dia. steel marker extending 4' above ground level w/location marked thereon. You will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>[Signature]</i></u>	TITLE Dist. Engineer	DATE 12-12-68
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u><i>[Signature]</i></u>	DATE <u><i>[Signature]</i></u>
CONDITIONS OF APPROVAL, IF ANY:		