

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6802

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY HOLE	7. Unit Agreement Name
2. Name of Operator MONSANTO COMPANY	8. Farm or Lease Name State "L"
3. Address of Operator 101 North Marienfeld, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER P , 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 10S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Undesignated Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4241' RKB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled to a total depth of 10,020', logged and found to be non-productive of oil or gas. Verbal permission to plug and abandon this well as follows was obtained from Mr. J. D. Ramey by Don Kolb on 10-24-68: Fill hole w/10# mud, set 25 sx cement plugs at following points: 10,020', 9850', 7750', 5450', 4000'. Shoot 8 5/8" casing at 1200' and pull. 25 sxs cement plugs at 1260' and 360'. 10 sx cement plug at surface w/4" dia-steel marker extending 4' above ground level set therein.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>W. W. Wood</i></u>	TITLE <u>Dist. Prod. Supt.</u>	DATE <u>10-30-68</u>
APPROVED BY <u><i>Joe D. Ramey</i></u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		