	·····				1	المريدين والمعمور
DISTRIBUTION		MEXICO OIL CONSEI				
SANTA FE	NC#	MEXICO UL CONSEI	CTATION COMMISSI		Form C-101 Revised 1-1-6	5
FILE	· + ·				5A. Indicate	Type of Lease
U.S.G.S.	+	(<u>)</u> ?			STATE	FEE
LAND OFFICE			• •	7.	.5. State Oil	& Gas Lease No.
OPERATOR					E-	9669
APPLICATION	N FOR PERMIT TO	DRILL, DEEPEN,	DR PLUG BACK		7. Unit Agre	ement Name
				_		
b. Type of Well DRILL		DEEPEN	PLU	G BACK	8. Form or L	ease Name
OIL X GAS WELL	OTHER		SINGLE N	ZONE	New Mex	ico "CC" State
2. Name of Operator					9. Well No.	
	E OIL & REFININ	IG COMPANY	•			4
3. Address of Operator						d Pool, or Wildcat
BOX 1600, MIDI					Inbe	Penn.
Location of Well UNIT LETTER	а <u> </u>	CATED 1,980 F	EET FROM THE <u>Wes</u>	StLINE	$\Delta M M$	
AND 2,086 FEET FROM T	Nonth	27	wp. 10-5 AGE. 3	00 E		
AND 2,000 PEET FROM T	THE North LI	NE OF SEC. 27 T	WP. 10-3 RGE. 3		12. County	
					Lea	
*******	******	*******	tittittitti	titititi.	mm//	iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii
		(111111111111111111111111111111111111	9. Proposed Depth	19A. Formatio	on	20. Rotary or C.T.
			9,800'	Penn.		Rotary
21. Elevations (Show whether DF,		t & Status Plug. Bond 2 et on file	1B. Drilling Contracto Unknown	r		. Date Work will start r 1, 1968
To be filed later			unknown			T T T T T 200
23.	ſ	PROPOSED CASING AND	CENENT PROCEAM			
			CEMENT I ROOKAM			
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT			F CEMENT	EST. TOP
SIZE OF HOLE	SIZE OF CASING		SETTING DEPT	TH SACKS O		· · · · · · · · · · · · · · · · · · ·
SIZE OF HOLE 15" 11"	SIZE OF CASING 11 3/4" 8 5/8"	WEIGHT PER FOOT 42# 24# & 32#	SETTING DEPT	гн sacks o 3 50		· · · · · · · · · · · · · · · · · · ·
15"	11 3/4"	42#	SETTING DEPT 350' 4,100'	гн sacks o 350 450	Sacks Sacks	· · · · · · · · · · · · · · · · · · ·
15" 11"	<u>11 3/4"</u> 8 5/8"	42# 24# & 32#	SETTING DEPT 350' 4,100'	гн sacks o 350 450	Sacks Sacks	Circ. to Surfac
<u>15"</u> <u>11"</u> 7 7/8"	11 3/4" 8 5/8" 5 1/2"	42# 24# & 32# 17#, 15.5# & 14#	SETTING DEPT 350' 4,100' 9,800	гн sacks o 350 450 325	Sacks Sacks Sacks	Circ. to Surfac * **
<u>15"</u> 11"	11 3/4" 8 5/8" 5 1/2"	42# 24# & 32# 17#, 15.5# & 14#	SETTING DEPT 350' 4,100' 9,800	гн sacks o 350 450 325	Sacks Sacks Sacks	Circ. to Surfac * **
15" 11" 7 7/8" *Circ. back to shoe.	<u>11 3/4"</u> <u>8 5/8"</u> 5 1/2" approximately	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen	TH SACKS O 350 450 325 It and us	Sacks Sacks Sacks e 200 sa	Circ. to Surfac ** cks neat around
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at	<u>11 3/4"</u> <u>8 5/8"</u> 5 1/2" approximately least 600 fee	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 It and us	Sacks Sacks Sacks e 200 sa	Circ. to Surfac ** cks neat around
15" 11" 7 7/8" *Circ. back to shoe,	<u>11 3/4"</u> <u>8 5/8"</u> 5 1/2" approximately least 600 fee	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 It and us	Sacks Sacks Sacks e 200 sa	Circ. to Surfac ** cks neat around
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of se 200 sacks ne	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 It and us	Sacks Sacks Sacks e 200 sa	Circ. to Surfac ** cks neat around
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of se 200 sacks ne	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 It and us	Sacks Sacks Sacks e 200 sa one, est	Circ. to Surfac ** cks neat around imated to be
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of e 200 sacks ne	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 It and us ost pay z	Sacks Sacks Sacks e 200 sa one, est	Circ. to Surfac ** cks neat around imated to be
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1	<u>11 3/4"</u> <u>8 5/8"</u> <u>5 1/2"</u> approximately least 600 fee 2% Gel and us ogram for sam f cementing t	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of te 200 sacks ne tples. o be used.	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 It and us ost pay z ioe.	Sacks Sacks Sacks e 200 sa one, est APPROVA OF 90 DAY	Circ. to Surfac ** cks neat around imated to be
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. to be used.	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 at and us ost pay z oe.	Sacks Sacks Sacks e 200 sa one, est APPROVA CP 90 DAY RILLING CO	Circ. to Surface ** cks neat around imated to be MALLS MALLS
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. to be used.	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 at and us ost pay z oe.	Sacks Sacks Sacks e 200 sa one, est APPROVA CP 90 DAY RILLING CO	Circ. to Surface ** cks neat around imated to be MALLS MALLS
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of te 200 sacks ne tples. o be used.	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo	TH SACKS O 350 450 325 at and us ost pay z oe.	Sacks Sacks Sacks e 200 sa one, est APPROVA CP 90 DAY RILLING CO	Circ. to Surfac ** cks neat around imated to be MALLO S UNLESC WMETHING
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of e 200 sacks ne aples. o be used. MACSION AUST S PEICE TO RUS	SETTING DEPT 350' 4,100' 9,800 8% Gel cemen the uppermo at around sh	TH SACKS O 350 450 325 at and us ost pay z oe.	Sacks Sacks Sacks e 200 sa one, est APPROVA COL 90 DAY RILLING COL S /2 -2	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COM OUR	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ t above top of e 200 sacks ne aples. o be used. MACSION AUST S PEICE TO RUS	SETTING DEPT 350' 4,100' 9,800 8% Gel cemen the uppermo at around sh	TH SACKS O 350 450 325 at and us ost pay z oe.	Sacks Sacks Sacks e 200 sa one, est APPROVA COL 90 DAY RILLING COL S /2 -2	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA COA COA COA COA COA COA COA	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. o be used. AMUSION AUST S PEICE TO RUS	SETTING DEPT 350' 4,100' 9,800 8% Gel cemen the uppermo eat around sh 1/3/2 PLUG BACK, GIVE DAT	TH SACKS O 350 450 325 at and us ost pay z oe.	Sacks Sacks Sacks e 200 sa one, est APPROVA COL 90 DAY RILLING COL S /2 -2	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA COA COA COA COA COA COA COA	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. o be used. AMASION AUST CS PEICE TO RUST PEICE TO DEEPEN O	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z ost pay z of <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL 90 DAY RILLING COL S /2 -2	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr Howco method o NABOVE SPACE DESCRIBE PR HOWCO method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA COA COA COA COA COA COA COA	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. o be used. AMUSION AUST S PEICE TO RUS	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z ost pay z of <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL 90 DAY RILLING COL S /2 -2	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/1 Minimum mud pr Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA OLA OPOSED PROGRAM: IF ER PROGRAM: IF ANY. m above is true and com	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. o be used. AMASION AUST CS PEICE TO RUST PEICE TO DEEPEN O	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z ost pay z of <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL SOF 90 DAY RILLING COL S	Circ. to Surface ** cks neat around imated to be MALLO S UNLESC VMET
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA OLA OPOSED PROGRAM: IF ER PROGRAM: IF ANY. m above is true and com	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. o be used. AMASION AUST CS PEICE TO RUST PEICE TO DEEPEN O	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z ost pay z of <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL SOF 90 DAY RILLING COL S	Circ. to Surface ** cks neat around imated to be VALID S UNLESC VMET
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o Howco method o	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA OLA OPOSED PROGRAM: IF ER PROGRAM: IF ANY. m above is true and com	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. o be used. AMASION AUST CS PEICE TO RUST PEICE TO DEEPEN O	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z oc <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL SOF 90 DAY RILLING COL S	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o Howco method o NABOVE SPACE DESCRIBE PR HOWCO method o This space for State of the space of	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA COA COA COA COA COA COA COA	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. 0 be used. AMASION MUST CS PEICE TO RUST PROPOSAL IS TO DEEPEN O mplete to the best of my k 	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z oc <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL SOF 90 DAY RILLING COL S	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o Howco method o Howco method o This space for State of the space for State of the space of th	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA COA COA COA COA COA COA COA	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. 0 be used. AMASION MUST CS PEICE TO RUST PROPOSAL IS TO DEEPEN O mplete to the best of my k 	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z oc <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL SOF 90 DAY RILLING COL S	Circ. to Surfac ** cks neat around imated to be VAUD S UNLESC VMED. 3-68
15" 11" 7 7/8" *Circ. back to shoe. **Circ. back at 8,000 feet w/l Minimum mud pr Howco method o Howco method o Howco method o This space for S This space for S	11 3/4" 8 5/8" 5 1/2" approximately least 600 fee 2% Gel and us ogram for sam f cementing t COA COA COA COA COA COA COA COA	42# 24# & 32# 17#, 15.5# & 14# 2,500 feet w/ at above top of e 200 sacks ne aples. 0 be used. AMASION MUST CS PEICE TO RUST PROPOSAL IS TO DEEPEN O mplete to the best of my k 	SETTING DEPT 350' 4,100' 9,800 '8% Gel cemen the uppermo eat around sh at around sh at around sh at around sh	TH SACKS O 350 450 325 at and us ost pay z ost pay z oc <i>SXPIRE</i>	Sacks Sacks Sacks e 200 sa one, est APPROVA COL SOF 90 DAY RILLING COL S	Circ. to Surfac ** cks neat around imated to be MALLO S UNLESC WMETHING