

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-1348	
7. Unit Agreement Name	
8. Farm or Lease Name	
Cabot State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Vada Pennsylvanian	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator
Texas Pacific Oil Company, Inc.
3. Address of Operator
P. O. Box 2621 Midland, Texas 79701
4. Location of Well
UNIT LETTER <u>D</u> <u>554</u> FEET FROM THE <u>N</u> LINE AND <u>554</u> FEET FROM THE <u>W</u> LINE, SECTION <u>29</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
4229 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☒
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled : by K. K. Amini 11-3-68
12 3/4" set at 370' w/ 375 sacks
8 5/8" set at 4060' w/400 sacks
top of cement 2000'
5" set at 10,030 w/400 sacks
top of cement 6300'
Perforation at 9960'-9971
5" colapsed on tubing and tubing colapsed
unable to recover, cut tubing off and
pulled from 9270'.

Prodedure for Pulling is:
Set CIBP at 9270' w/35' of cement on top
Mud Hole
Shoot off 5" casing
set 100' plug at 5" casing stub
set 100' plug at 7750' if 5" recovered
below
set 100' plug at 5460' if 5" recovered
below
set 100' plug at 4100' base of 8 5/8"
Shoot off 8 5/8" casing if possible
Set 100' plug at 3 5/8" stub
Set 100' plug at 385' base of 12 3/4"
Set 10 sacks plug at surface w/marker.

* IF 8 5/8" IS PULLED BELOW SALT SECTION THE
SALT SECTION MUST BE ISOLATED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

J. R. Stibney

TITLE Agent

DATE 11-3-75

APPROVED BY

Jerry Sexton

SUPERVISOR DISTRICT

DATE

NOV 5 1975

CONDITIONS OF APPROVAL, IF ANY: