•		
<b>**</b>		ALC: NO.
N OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
ANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
ILE		
	<b>-</b>	5a. Indicate Type of Lease
AND OFFICE X		State X Foo
PERATOR		5. State Cil & Gas Lease No.
	- <b>-</b>	LG 3814
SUND	ORY NOTICES AND REPORTS ON WELLS HOPOSALS TO DHILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVO ATION FOR PERMIT - FORM C-1011 FOR SUCH PROPOSALS.)	т.
OIL X GAS WELL X	OTHER-	7. Unit Agreement Name
Came of Cperator		8, Farm or Lease Name
The Maurice L. Br	rown Company	T.P. State
Address of Operator	July July 1	9. Well No.
Suite 200/Sutton	Place Bldg. Wichita, Kansas 6720	02 1 7
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	1980 FEET FROM THE South LINE AND 660	- FIET FROM Vada Penn
THE East LINE, SEC	TION 25 TOWNSHIP 10-S RANGE 33-E	MARIENT AND
	15. Elevation (Show whether DF, RT, GR, etc.) 4229 ** GR	Lea
	Appropriate Box To Indicate Nature of Notice, Rep	ort or Other Data assequent report of:
NOTICE OF	INTENTION TO: SUB	SEGULITI NES ONT OUS
PLRFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT J	· · · · · · · · · · · · · · · · · · ·
OTHER		
8-26-81 Spotted	Operations (Clearly state all pertinent details, and give pertinent date 31 sacks cement through drill pipe casing at 3510'. Tagged top of cemed to salvage 8 5/8" casing from sli	ent with wire line at 3460 ip joint at 1234'. Could

8-26-8! Spotted 31 sacks cement through drill pipe at 3570' across top of 5 1/2" casing at 3510'. Tagged top of cement with wire line at 3460'.
8-27-81 Attempted to salvage 8 5/8" casing from slip joint at 1234'. Could not pull with 100,000# strain. Spotted 40 sacks cement through tubing at 1285'. Displaced with 6 barrels mud. Laid down drill pipe. Shot 8 5/8" casing in collar at 1018'. Started laying down 8 5/8" casing.
8-28-81 Laid down 45 joints plus top piece of 8 5/8" casing. Total tally of 1035.81'. Spotted 60 sacks cement at 1068' depth and displaced with 5 barrels mud. Tagged top of cement at 940' with wire line. Spotted 65 sacks cement through drill pipe at 430'. Laid down drill pipe.
8-29-81 Tagged top of cement with wire line at 381'. Ran tubing to 381'. Spotted 50 sacks cement at 381'. Laid down tubing.
8-31-81 Tagged top of cement with wire line at 230' depth. Set 10 sacks cement plug at surface. Erected dry hole marker. Rigged down PBCP Services, Inc.

I hereby certify that the information above is true and complete	te to the best of my knowledge and belief.	
	District Engineer	8-31-81
ALPROVED OF AND PORTOR	OIL & GAS INSPECTOR	