

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1a. Type of Lease	State <u>63</u>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-5332		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole P&A</u>	7. Unit Agreement Name
2. Name of Operator <u>BTA Oil Producers</u>	8. Farm or Lease Name <u>Capitan 687 Ltd.</u>
3. Address of Operator <u>104 South Pecos, Midland, Texas 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>9-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Middle Allison Penn</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4140' G.L.</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-21-69: Set bridge plug @ 9000' w/1 sx cmt.
Cut 5½" csg. @ 7600'
Put 25 sx Cmt. @ 5½" stub
Put 25 sx Cmt. @ 5478'
Put 25 sx. Cmt. @ 4100'
Cut 8-5/8" csg. @ 1240'
Put 25 sx Cmt. @ 8-5/8" stub
Put 25 sx Cmt. @ 375'
Put 10 sx Cmt. @ Surface
Install dry hole marker per NMOCC regulations
P&A complete 5-21-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Drilling Manager

DATE 6-20-69

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____