

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

970 APR 9 AM 8 14

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2217 & OG-5002
7. Unit Agreement Name
8. Farm or Lease Name State "M"
9. Well No. 1
10. Field and Pool, or Wildcat Vada Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Monsanto Company
3. Address of Operator 101 North Marienfeld, Midland, Texas 79701
4. Location of Well UNIT LETTER A 510 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 10 S RANGE 34E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4263 RKB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled to a total depth of 9975' with 5½" casing set at 9972'. The well was completed and has since declined to be non-productive of oil and gas. The well will be plugged and abandoned in the following manner:

1. 35 sxs. cement plug across perforations 9880 to 9890.
2. Hole circulated with mud.
3. 5½" casing shot off and pulled.
4. 25 sxs. cement plug across 5½" casing stub.
5. 25 sxs. cement plug across top of Glorieta (5450').
6. 25 sxs. cement plug across 8-5/8" casing shoe.
7. 8-5/8" casing shot off and pulled.
8. 25 sxs. cement plug across 8-5/8" casing stub.
9. 25 sxs. cement plug across 11-3/4" casing shoe.
10. 10 sxs. cement plug at surface with 4" dia-Steel marker extending 4' above ground level set there in.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. W. Wood **A. W. Wood** TITLE **District Production Manager** DATE **April 8, 1970**

APPROVED BY [Signature] TITLE **SUPERVISOR DISTRICT** DATE **APR 12 1970**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 1 1970

PHOTOGRAPHY SECTION