

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5353	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name -
2. Name of Operator Sun Oil Company		8. Farm or Lease Name State Tract "D"
3. Address of Operator P. O. Box 1861, Midland, Texas 79701		9. Well No. 3
4. Location of Well UNIT LETTER <u>B</u> <u>510</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>11-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) GR 4203.5		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) 7-7-72 Halliburton sptd. 6 sx. sd. @ 9865-9816 & 50 sx. cmt. plug 9865-9445.
- (2) 7-17-72 Bonanza MIRU.
- (3) 7-19-72 Sht. 5½" csg. @ 5599. Stuck.
- (4) 7-20-72 Released stuck 5½" csg. Pull & LD. Circ. 9.5# mud.
- (5) 7-21-72 Sptd. 50 sx. cmt. plug 5600-5460 & 75 sx. cmt. plug 4151-3940.
- (6) 7-22-72 Sht. 8-5/8" csg. @ 1005.
- (7) 7-24-72 Sptd. 70 sx. cmt. plug 1005-900 & 75 sx. cmt. plug 450-335.  
Set 10 sx. cmt. plug to surf. Install P&A marker - Complete -

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles Gray</u>	TITLE <u>Proration Clerk</u>	DATE <u>8-3-72</u>
APPROVED BY <u>Nathan E. Clegg</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		