DISTRIBUTION	-1		Form C-103	
			Supersedes Old C-102 and C-103	
	NEW WEXICO OIL CON	SERVATION COMMISSION	Effective 1-1-65	
SANTA FE	1			
FILE	-		5a. Indicate Type of Lease	
U.S.G.S.	-	· ·	State	Fee.
LAND OFFICE	-		5. State Oil & Gas Lease N	٥.
OPERATOR	_1			
CINID	DY MOTICES AND REPORTS OF	JWELLS		<i>VIIII</i> 1.
SUNU (EO NOT USE THIS FORM FOR PI	RY NOTICES AND REPORTS ON ROPOSALS TO DRILL OR TO DEEPEN OR PLUG	BACK TO A DIFFERENT RESERVOIR.		
1.	TION FOR PERMIT _ (FORM O FOR)		7. Unit Agreement Name	
OIL GAS WELL	OTHER-			
2. Name of Operator			8. Farm or Lease Name	
Stolts & Compan	<b>Y</b>		Zelda	
3. Address of Operator			9. Well No.	İ
e/e Oil Reports	& Gas Services, Box 763,	Hobbs, New Mexico	1	
4. Location o Well			10. Field and Pool, or Wild	1
P. Location of word	660 FEET FROM THE South	660 FEET FRO	Undes M.Bagley L.	Penn
UNIT LETTER	FEET FROM THE	LINE AND		
Total	10 11	S RANGE 33 B NMPM		1111111
THE LINE, SEC	TION TOWNSHIP	RANGE		7/////
mmmmm	15. Elevation (Show whether	er DF, RT, GR, etc.)	12. County	HIIII.
	4309 GL		Lea	7/////
	Appropriate Box To Indicate	Nature of Notice Report of O	ther Data	
		Nature of Notice, Report of O	IT REPORT OF:	
NOTICE OF	INTENTION TO:	308324021		
		REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABAND	$\overline{}$
TEMPORARILY ABANDON	۲	CASING TEST AND CEMENT JOB	, <b>-0</b>	
PULL OR ALT IR CASING	(HANGE PLANS	OTHER		
	_	7		
OTHER		<b>-</b>		
Township of Completed	Operations (Clearly state all pertinent d	etails, and give pertinent dates, including	ng estimated date of starting a	ny proposed
woc 18 hours an	/28/68. Comented 13 3/8" sealcium chloride. Comented tested casing with 100 32# & 24# J-55 casing a	of for 30 minutes, test	0.K.	•
chleride. Plug 30 minutes, tes Cemented 4 1/2"	t 0.K.  N-80 11.6# easing at 10 8# salt per sack. Flug h 1,000# for 30 minutes,	,412 feet with 500 sacks down 1:45 PM 1/23/69. W	50/50 Incor	
chleride. Plug 30 minutes, tes Cemented 4 1/2" Fogmix, 25 gel, test easing wit	t 0.K.  N-80 11.6# easing at 10 8# salt per sack. Plug	,412 feet with 500 sacks deum 1:45 PM 1/23/69. Wo test 0.K.	50/50 Incor	2
commended 4 1/2"  Commented 4 1/2"  Posmix, 25 gel, test easing wit	N-80 11.6# casing at 10 8# selt per sack. Flug h 1,000# for 30 minutes,	deum 1:45 PM 1/23/69. Wo test 0.K.	50/50 Incor C 48 hours and	
commended 4 1/2"  Commented 4 1/2"  Posmix, 25 gel, test easing wit	N-80 11.6 casing at 10 8 salt per sack. Plug h 1,000 for 30 minutes,	deum 1:45 PM 1/23/69. Wo test 0.K.	50/50 Incor C 48 hours and	EDOS
chleride. Plug 30 minutes, tee  Comented 4 1/2" Formix, 25 gel, test easing wit	N-80 11.6# casing at 10 8# selt per sack. Flug h 1,000# for 30 minutes,	deem 1:45 PM 1/23/69. Wo test 0.K.	50/50 Incor C 48 hours and	
cemented 4 1/2"  Comented 4 1/2"  Posmix, 25 gal,  test easing wit	N-80 11.6# easing at 10 8# salt per sack. Plug h 1,000# for 30 minutes,	deem 1:45 PM 1/23/69. Wo test 0.K.	50/50 Incor C 48 hours and	