	<del></del>		
NO. OF COPIES RECEIVED		Form C-103 Supersedes Old	
DISTRIBUTION		C-102 and C-103	
SANTA FE	NEW MEXICO OIL CONSERVATION C	COMMISSION Effective 1-1-65	
FILE		5a. Indicate Type of Lease	
J.S.G.S.		57	Fee
LAND OFFICE		5. State Oil & Gas Lease N	
OPERATOR		K-117	
			111111
(DO NOT USE THIS	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFE SE "APPLICATION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	ERENT RESERVOIR.	
		7. Unit Agreement Name <b>NONE</b>	
2. Name of Operator		8. Farm or Lease Name	
ROGER C.	HANKS	Fina-State	
3. Address of Operator		9. Well No.	1
	& Gas Building, Wichita Falls, Te	xas 76301 1	
4. Location of Well		10. Field and Pool, or Wild	
UNIT LETTER	1980 FEET FROM THE South LINE AND	660 FEET FROM Undesignated	·····
			111111
East	LINE, SECTION 10 TOWNSHIP 105 RANGE	32E NMPM.	.///////
IHE			HHHH
	15. Elevation (Show whether DF, RT, GR,	etc.) 12. County	
	4324 GL	Lea	711111
16.	Check Appropriate Box To Indicate Nature of N	otice. Report or Other Data	
NO	TICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
NO	TICE OF INTERTION TO:		
	PLUG AND ABANDON REMEDIAL W	ORK ALTERING CASING	G 🗌
PERFORM REMEDIAL WORK		DRILLING OPNS.	ONMENT
TEMPORARILY ABANDON		T AND CEMENT JOB	
PULL OR ALTER CASING		Supplemental report on compl	.etion
OTHER			
17. Describe Proposed or work) SEE RULE 110	Completed Operations (Clearly state all pertinent details, and give	pertinent dates, including estimated date of starting as	ny proposed
,	Ran cement bond log and collar lo	cator log	
	Ran cement bond toy and correct to	m = 90131 KBM	
2-25-69	Picked up tubing and tagged botto	amplied to the ant of the	aina
2-26-69	Displaced hole with fresh water,	wyuaiizeu 7 in 7 vut di tur	1911Å
<b>_</b>	1000 gal. 15% non-emulsifying dou	IDIE TUUTDICES CCTS.	a
2-27-69	Perforated first zone 8970' to 89	150. 7 SUOTS DEL LOOF IN SCI	.a.
2-28/	Commenced swabbing for production	) tests.	

·**~** .

3-6-69 Swabbing. 3-7/

3-10-69 Waiting on orders.
3-11-69 Moved on well service unit, pulled tubing; preparing to perforate.
3-12-69 Perforated 8917' to 8935', 2 shots per foot and 1000 gallons 15% NE acid equalized 1/2 in 1/2 out of tubing.

3-13/ 3-14 Swabbing for production tests.

18. I have by certify that the information above is true and complete to the bes	at of my knowledge and belief.	
$(   \Omega   ( ) \Omega )$		DATE March 15, 1969
artin in Russian		JUL
CONDITIONS CAPPROVAL, IF ANY:		