

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Plan approved
Budget Plan No. 42, R-121
Date of Plan Approved: 5-22-1973
NM 0396347

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposal.

1. WELL TYPE
X GAS WELL OTHER

2. NAME OF OPERATOR

Apache Exploration Corporation

3. ADDRESS OF OPERATOR

P. O. Box 2299, Tulsa, Oklahoma 74101

4. LOCATION OF WELL Report location clearly and in accordance with any State requirements.
State also shown below.
At surface

1980' FNL & 1980' FWL of Sec. 1-T9S-R35E

5. DRILLING NO.

6. PERIODIC CHECKS (Check if applicable)

GR 4127

7.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUTOFF

SHUT OFF AFTER CASING

SHUT OFF IF POSSIBLE

RESULTS OF

FLUID TREATMENT

REMOVING OF RESIDUE

FLUID TREATMENT

IN SITU TEST

SURFACE SPILLS

LEAKS

SHUTTING OFF A HOLE

EXPERIMENT

REPAIR WELL

REMOVING OF RESIDUE

TESTING

TESTING

OTHER

TESTING

TESTING

17. Work began approximately one month ago. Clearly state the nature of wells, and other pertinent data, and date estimated date of starting and completion work. If well is directionally drilled, give subsurface location and the general and true vertical depths of bottom markers and zones penetrated to this work.

Work began Aug. 14 and was completed Aug. 21, 1972

- (1) Cut 2" tubing at 9505' (Could not unlatch off and on tool.)
- (2) Circulate well with 10.5# mud laden fluid (10.5 mud)
- (3) Spotted 200' cement plug on packer
- (4) Shot 5 1/2" OD casing at 4504'. Pipe was free. 5,546' of 5 1/2" csg. was left in the hole to a depth of 10,050 ft.
- (5) Pumped 35 sack cement plug at 4475'
- (6) Pumped 35 sack cement plug at 4,000' (Shoe of 3 5/8" casing)
- (7) Shot 3 5/8" OD casing at 1,500'. 2,600' of 3 5/8" csg. was left in the hole to a depth of 4,200 ft.
- (8) Ran tubing and pumped 100' cement plug at top of cut in 3 5/8" csg.
- (9) Pumped 100' cement plug at bottom of surface pipe
- (10) Set 10 sack cement top plug
- (11) Installed regulation dry hole marker
- (12) Pits were filled and the location levelled and cleared of junk

Apache Exploration respectfully requests your inspection of the location.

18. I hereby certify that the foregoing is true and correct.

SIGNED: *JULY 16, 1973* by *Regional Production Adm.*

This space for Federal or State signature

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

