

District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-22988
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	TANKERSLEY
8. Well No.	3
9. Pool name or Wildcat	Strawn SWD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW - SI	
2. Name of Operator	Saga Petroleum LLC
3. Address of Operator	415 W. Wall, Suite 1900 Midland, TX 79701
4. Well Location	
Unit Letter F	1980 feet from the N line and 1965 feet from the W line
Section 30	Township 9S Range 34E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐
OTHER: MIT-TA ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

9-11 RIH w/4-3/4" bit, 5-1/2" csg scraper, jars, DC's & WS. 10:20 AM had pkr pushed down to 8527', start pumping soapy wtr & pushed pkr down. @ 12:00 pm had pkr down to 9307'. RU power swivel & attempted drlg pkr down, could not get pkr to move. POOH w/fishing tools & WS & SDFN

9-12 RIH w/1-1/4" x 3-1/8" tapered tap, 3-3/4" bit subs, 3-3/4" jars, 4- 3-1/2" DC's & WS to 9307'. Tapped into pkr & jarred loose, POOH w/tools & pkr. RIH w/4-3/4" jars, 4- 3-1/2" DC's & WS, tag @ 9815', pulled above perms & SDFN. Btm perms @ 9803'.

9-13 POOH w/WS, LD tools & DC's. Pumped 130 bbls fresh wtr & soap down csg. RIH w/5-1/2" CIBP & set @ 9706'. (309 jts) Pumped 130 BFW w/1/2 drum pkr fluid. POOH w/50 jts tbg. SDON. Prep to continue LD WS today

9-14 POOH w/WS, ND BOP, NUWH, load well w/pkr fluid, took 87 bbls to load, Took total 87 bbls to load csg. RD. Press test to 500 psi. went from 520 psi to 560 psi in 15 mins. Bled down & had foamy pkr fluid. Reload

9-18-02 Press up to 560 psi - held for 30 mins - good test - chart attached - Well TA'd w/good MIT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 09/23/2002

Type or print name Bonnie Husband Telephone No. (915)684-4293

(This space for State use) ORIGINAL SIGNED BY
GARY W. WINK

APPROVED BY OC FIELD REPRESENTATIVE DATE SEP 26 2002

Conditions of approval, if any:

This Approval of Temporary
Abandonment Expires 9/25/07

