

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.	30-025-22988
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name TANKERSLEY	
8. Well No.	3
9. Pool name or Wildcat Strawn SWD	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW - SI	
2. Name of Operator Saga Petroleum LLC	
3. Address of Operator 415 W. Wall, Suite 1900 Midland, TX 79701	
4. Well Location Unit Letter F : 1980 feet from the N line and 1965 feet from the W line Section 30 Township 9S Range 34E NMPM County Lea	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

3-11-02 MIT Failure -well would not pressure up

9-04-02 MIRU, NDWH, Install BOP, POOH & LD 168 jts 2-7/8" IPC tbg. Tbg scaled up on outside PU OS & WS & RIH, tag up @ 5470'. Attempt to catch tbg fish, could not.

9-05 RIH w/4-3/4" OS, top of fish @ 5470'. Latch on to fish. RU WL, RIH w/1-1/2" sub-bars, tag @ 7477' & push to 7557'. Pumped 70 bbls hot soapy wtr dwn tbg. RIH w/free-point-tool & tag @ 7533'. PU to 7528', did free point & was free @ 7528'. RIH w/spud-bars & worked past tight spot @ 7533'. RIH to 9870' PBT. Pumped 60 bbls soapy wtr dwn csg. Attempted to release pkr & could not get loose. RIH w/1-1/2" line-shot & could not get pass 7533'

9-06 RIH w/1" line-shot & work thru tight spot @ 7533'. POOH, RIH, found pkr @ 8466', back off 2-7/8" PC tbg 1 jt above pkr @ 8438'. POOH, standing back WS. LD 263 jts 2-7/8" PC tbg
Continued on back

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst

DATE 09/11/2002

Type or print name Bonnie Husband

Telephone No. (915)684-4293

(This space for State use) ORIGINAL SIGNED BY

APPROVED BY GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE SEP 18 2002

Conditions of approval, if any:

SEP 18 2002

- 9-07 RIH w/4-5/9" notched shoe, 1 jt 4-5/8" WP & 6- 3-1/2" RC's. Tag up @ 8433', pump 100 bbls dwn csg. Drld out 2' in 1.5 hrs, fell thru to 5' to 8,440', milled 1', stopped making hole, could be on pkr @ 8,441'. POOH w/WS, collars, WP & shoe. SDFW. Pumped total 350 bbls of wtr.
- 9-10 RIH w/4-11/16" OS, 3-3/4" BS, 3-3/4" jars, 4- 3-1/2" DC's, 3-3/4" excalator. **Tight spots @ 8383', 8412'. Tag top of fish @ 8426'.** Latch on & work pkr loose. POOH & had top sub & 3" of mandrel SDFN. Pumped 50 BW
- 9-11 RIH w/4-3/4" bit, 5-1/2" csg scraper, jars, DC's & WS. 10:20 AM had pkr pushed dwn to 8527', start pumping soapy wtr & pushed pkr dwn. @ 12:00 pm had pkr dwn to 9307'. RU power swivel & attempted drlg pkr dwn, could not get pkr to move. POOH w/fishing tools & WS & SDFN



