STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MO. OF COPIES RUCCIVES	<u> </u>	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
		i

OIL CONSERVATION DIVISION

Rig up. Check tubing and pump. Run packer. Acidize Bough 'C' perfs. with 2000 gallons 20% NEFE acid. Return well to production.		
Check tubing and pump. Run packer. Acidize Bough 'C' perfs. with 2000 gallons 20% NEFE acid.		
Check tubing and pump. Run packer. Acidize Bough 'C' perfs. with 2000 gallons 20% NEFE acid.		
Check tubing and pump. Run packer. Acidize Bough 'C' perfs. with 2000 gallons 20% NEFE acid.		
Check tubing and pump. Run packer. Acidize Bough 'C' perfs. with 2000 gallons 20% NEFE acid.		
work) SEE NOCE 1155		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluork) SEE RULE 1703.	uding estimated date of starting any propos	
OTHER		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING PLUG AND ABANDONMENT	
Check Appropriate Box To Indicate Nature of Notice, Report of Notice of Intention To:	Other Data	
15. Elevation (Show whether DF, RT, GR, etc.) 4299.8	12. County LEA	
0 34	MPM.	
4. Location of Well F 1980 NORTH 1965	10. Field and Pool, or Wildcat VADA PENN	
P. O. BOX 5970 HOBBS, NEW MEXICO 88241	9. Well No.	
PENROC OIL CORPORATION	TANKERSLEY	
I. OIL X GAS OTHER-	7. Unit Agreement Name 8. Farm or Lease Name	
SUNDRY NOTICES AND REPORTS ON WELLS GOD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFFER ON PLUG EACH TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
	State Fee X 5. State Oil & Gas Lease No.	
LAND OFFICE OPERATOR		
LAND OFFICE	5a. Indicate Type of Lease	

APPROVED BY DISTRICT | SUPERVISOR TITLE