

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 22991

30-025-22391

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Christie

8. Well No.

1

9. Pool name or Wildcat

No Bagley Perm
Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐			
2. Name of Operator <u>Smith & Mairs, Inc</u>			
3. Address of Operator <u>Box 863 Kermit, TX. 79745</u>			
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>11 S</u> Range <u>33 E</u> NMPM <u>LEA</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4309' AR</u>			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 9320' - 35' cmt on top - TAG
2. 25 sxs @ 7330 - 7230 (HAW)
3. 25 sxs @ 5138 - 5038 (HAW)
4. 35 sxs @ 50' in & 50' out 4 1/2 casing stub - 4500' - TAG
5. 40 sxs @ 3800 - 3700' & tag - 3 3/8 shoe @ 3750' - TAG
6. 35 sxs @ 2200 - 2100' - (GAT)
7. Pull 3 3/8 @ 600' - , 50' in & 50' out stub
8. 50 sxs @ 350 - 250' - 13 3/8 shoe @ 300' TAG
9. 10 sxs @ 30' surface

Install Dry Hole Marker - Cir 9.5 MVD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

[Signature]

TITLE

Pres.

DATE

10-29-01

TYPE OR PRINT NAME

Rickey Smith

TELEPHONE NO.

915-586-3076

(This space for State Use)

APPROVED BY

TITLE

ORIGINAL SIGNED BY

DATE

NOV 06 2001

GARY W. WINK

NATURAL SCIENCE MANAGER - 2

(CONDITIONS OF APPROVAL, IF ANY)