

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION  
JUN 4 2 20 PM '69

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. -
7. Unit Agreement Name -
8. Farm or Lease Name Schmidt
9. Well No. 1
10. Field and Pool, or Wildcat Vada
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Charles B Read
3. Address of Operator P.O. Box 2126, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER H, 1980 FEET FROM THE North LINE AND 510 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 9S RANGE 34E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4242.5' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Fill hole with good mud.

Set 25 sx. plug	9660-9760'
Set 25 sx. plug	8110-8210'
Set 25 sx. plug	7740-7840'
Set 25 sx. plug	5291-5391'
Set 25 sx. plug	4020-4120'

Cut 8 5/8" casing @ 1550'; pulled casing.

Set 25 sx. plug	1500-1600'
Set 25 sx. plug	362-462'
Set 10 sx. plug	0 -10'

Installed regulation marker.  
Will notify when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John W. Runyan</u>	TITLE <u>Agent</u>	DATE <u>6/2/69</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: