NO. OF COPIES RECEIVE	0	HOSBS OFF	05 0. C. C.	Form C-103
DISTRIBUTION			*** ***	Supersedes Old C-102 and C-103
SANTA FE	N	IEM WEXICO OIL COMS	ERVATION COMMISSION	Effective 1-1-65
FILE				5a. Indicate Type of Lease
U.S.G.S.				State Fee X
OPERATOR				5. State Oil & Gas Lease No.
				_
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)				
1.  OIL X	GAS OTHER-			7. Unit Agreement Name
2. Name of Operator				8. Farm or Lease Name
Charles B. Read				Schmidt
3. Address of Operator				9. Well No.
P. O. Box 2126, Roswell, New Mexico 88201				1
4. Location of Well  UNIT LETTER H 1980 FEET FROM THE North LINE AND 510 FEET FROM				10. Field and Pool, or Wildcat Undesignated
UNIT LETTERH	FEET FROM TITTITITITITITITITITITITITITITITITITIT			
East	10	9.5		
THE	LINE, SECTION	TOWNSHIP	RANGE	— NMPM.
mmmm	1. (11111111111111111111111111111111111	. Elevation (Show whether	DF, RT, GR, etc.)	12, County
		4242.	5' GL	Lea
16.	Check Appropriate	e Box To Indicate N	ature of Notice, Repor	t or Other Data
NC	TICE OF INTENTION			EQUENT REPORT OF:
PERFORM REMEDIAL WORK	, <u> </u>	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOS	
			OTHER	
OTHER				
17. Describe Proposed of work) SEE RULE 11		arly state all pertinent deta	ails, and give pertinent dates,	including estimated date of starting any proposed
5-2-69:	Spudded @ 4:00	P.M.		
Ran 10 jts, 12 3/4", 34#, FWPS csg. 392.34' set @ 375' RKB. Cmt w/375 sx Class C, w/2% CaCl. Plug down @ 11:20 P.M. Cmt circ to surface. WOC 18 hrs. Press test to 1500# for 30 min. Test OK.				
18. I nereby certify that	the information above is trut	s and complete to the best	or my knowledge and belief.	
SIGNED & TO	wolf the	TIPLE	Operator	. DATE 5-5-69
$\bigcap$			-ಇಗೆಕ್ಟ್	47 7800

· ~ 📆