STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIED ACCEIVED	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.a.S.	Ţ	
LAND OFFICE		
OPERATOR	j	

OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BO	X 2088	Form C=103		
SANTA PE	SANTA FE, NEW	MEXICO 87501	Revised 10-1-7:		
FILE			Sa. Indicate Type of Leise		
U.S.O.S.	•		State Foo X		
LAND OFFICE			5, State Oil & Gas Lease No.		
DERATOR			5, claic (ii (i das 2, das 110.		
			Ammmmmm.		
SUNDRY	NOTICES AND REPORTS ON	WELLS			
USE "APPLICATIO	H FOR PERMIT -" (FORM C-101) FOR SUC	H PROPUSALS.)	<u> </u>		
11.			7. Unit Agreement Name		
weit X	OTHER-		1		
2. Name of Operator			9. Farm or Lease Name		
Texaco Inc.			F. B. Gist		
1, Address of Operator			9. Well No.		
PO Box 728, Hobbs, New Mexico 88240			1		
4. Location of Well			10. Ffeld and Pool, or Wildcat		
1	660	•	· ·		
UNIT LETTER A	660 FEET FROM THE Nort	h LINE AND 660 FEET FRE	N. Bagley Permo Pe		
					
THE East LINE SECTION	31 TOWNSHIP 1	19 33E			
THE	TOWNSHIP	TD RANGE HMP			
THITTINITE THE	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
	4314' DF	,			
<u>. , , , , , , , , , , , , , , , , , , ,</u>			Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
Check A	ppropriate Box To Indicate N	lature of Notice, Report or C	Other Data		
NOTICE OF IN			NT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
Ħ	7 200 A 10 A DANGON				
TEMPORARILY ABANDON	r	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	arilv Abandon		
<i>t</i> ,		OTHER TEMBOT	arily Abandon X		
OTHER					
 Describe Proposed or Completed Ope work) SEE RULE 1603. 	rations (Clearly state all pertinent dete	ails, and give pertinent dates, includi	ng estimated date of starting any proposea		
2000, 022 0022 0000					
DECTACCTEV EDOM CT	OTI MO ACD (ADAMDON		:		
RECLASSIFY FROM SI-OIL TO ASD (ABANDONED, SALVAGE-DEFERRED) STATUS					
EFFECTIVE 5/21/39.					
	·				
. 1) MIRU pulling ur	nit. Pull rods and	pump. Install BOP.	Pull tubing.		
	• •				
2) By wireline, se	et CIBP in 4 1/2" ca	sing at 9015! Hei	na dumn bailer		
	th 50' of cement. P	pmD. 0065!	ng damp barrer,		
ougged Cibs Wit	m 30 Of Cement.	BID. 6505 .	•		
3) RIH with tubing	. Tood belo with i	- 1- 2 1- 2 1 - 2 1			
3) RIH with tubing. Load hole with inhibited water. Test casing to 500 psi, OK. POH. Rig down pulling unit.					
500 psi, Ok.	OH. RIG down pulli	ng unit.			
•					
	•				
-					
10.1					
18. I hereby certify that the information a	nove is true and complete to the best of	or my knowledge and belief.	397-3571		
1.11	/	•	•		
Makeal /	Но	bbs Area Superinten	dent _{***} 6/3/88		
	BY JERRY SEXTON		**************************************		
取りますた ごうしき	の対象をないに合意		11 121 4 A 4000		