

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

FE-
re-

Form approved 30-025-23132
Budget Bureau No. 1004-01
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> Temporarily Abandoned Oil Well	5. LEASE DESIGNATION AND SERIAL NO NM71790
2. NAME OF OPERATOR Beach Exploration, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME ---
3. ADDRESS OF OPERATOR 800 N. Marienfeld Ste. 200 Midland, Texas 79701	7. UNIT AGREEMENT NAME ---
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FEL (Unit O)	8. FARM OR LEASE NAME Wolf Federal
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT Vada Penn
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5, T9S, R35E
	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☒

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Beach has the lease on which this well is located, and proposes to plug and abandon it. The well was originally drilled by Tenneco in 1969 as the Wolf Federal #1, API #30-025-23152.

Proposed Plug and Abandon Procedure:

1. Set CIBP @9,750'. Cap with 35' cement. (dump bailer)
2. Cut off 5 1/2" casing at free point (Top of cement is 8,640') and pull same.
3. Mud up hole with 9.5#/gal.
4. Spot 100' plug (30 sacks) across 5 1/2" casing stub (50' in 50' out).
5. Spot 100' plug (45 sacks) at 4,110' (50' above and below 8 5/8" shoe)
6. Spot 100' plug (45 sacks) at 820' (top salt).
7. Spot 100' plug (45 sacks) @422' (Across 13 3/8" shoe depth).
8. Spot 50' plug (23 sacks) @50'.
9. Cut off wellhead, set marker.

Anticipated date of plugging: 5-15-93

RECEIVED
APR 1 11 05 AM '93
OFFICE OF THE ATTORNEY GENERAL

18. I hereby certify that the foregoing is true and correct

SIGNED Hal Gill

TITLE Engineer

DATE 3-24-93

(This space for Federal or State office use)

APPROVED BY (ORIG. SEC.) JOE G. LARA
CONDITIONS OF APPROVAL, IF ANY:

TITLE PETROLEUM ENGINEER

DATE 5/3/93