

COPIES RECEIVED		
CONTRIBUTION		
NT & FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Marks & Garner Production Company 3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240 4. Location of Well UNIT LETTER <u>D</u> <u>554</u> FEET FROM THE <u>North</u> LINE AND <u>554</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>9S</u> RANGE <u>34E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4208.2 GR	7. Unit Agreement Name 8. Farm or Lease Name Irene Clark 9. Well No. 1 10. Field and Pool, or Wildcat Vada Penn 12. County Lea
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well plugged & abandoned as follows:

Set CIBP @ 9790 & capped with 35' cement
Unable to load hole with mud
Set CIBP @ 9700 & capped with 35' cement
Loaded hole with mud
Shot & pulled 4 1/2" casing from 4513
Spot 35 sack cement plug @ 4553
Tag top of plug at 4443 with wire line
Spot 35 sack cement plug at 4091
Spot 35 sack cement plug @ 2150
Shot & pulled 8 5/8" casing from 1003
Spot 45 sack cement plug @ 1053
Tag top of plug @ 918 with wire line
Spot 75 sack cement plug @ 444
Set 10 sack plug at surface with regulation marker
Job complete 12/30/80
Location is cleaned & levelled & ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan Walker TITLE Agent DATE 4/6/81

APPROVED BY Ronald C. Williams TITLE OIL & GAS INSPECTOR DATE JUN 16 1981

CONDITIONS OF APPROVAL, IF ANY: