

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. Name of Operator
Marks & Garner Production Company

2. Address of Operator
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240

4. Location of Well
UNIT LETTER D 554 FEET FROM THE North LINE AND 554 FEET FROM
THE West LINE, SECTION 13 TOWNSHIP 9 S RANGE 34 E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Irene Clark

9. Well No.
1

10. Field and Pool, or Wildcat
Vada Penn

12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
4208.2 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/9/78 Perforated 9808 to 9816 with 12 shots & treated with 6,000 gallons 20% acid. Ran rods and pump. Pumped 2 bbls oil and 2 bbls water per day.

It is now proposed to plug as follows:

Set CIBP @ 9790 & cap with 35' cement
Cut & pull 4 1/2" casing from approx 5000
Spot 100' cement plug across 4 1/2" casing stub
Spot 100' cement plug across 8 5/8" casing shoe @ 4041
Cut & pull 8 5/8" casing from approx 1200
Spot 100' cement plug 8 5/8" casing stub
Spot 100' cement plug across 13 3/8" casing shoe @ 394
10 sack plug at surface with regulation marker
Mud between all plugs.

3. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 11/13/80

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: