

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No.
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <b>Imperial-American Management Co.</b> 3. Address of Operator <b>507 Midland Savings Bldg., Midland, Texas 79701</b> 4. Location of Well UNIT LETTER <b>0</b> <b>1980</b> FEET FROM THE <b>East</b> LINE AND <b>720</b> FEET FROM THE <b>South</b> LINE, SECTION <b>4</b> TOWNSHIP <b>10-S</b> RANGE <b>34-E</b> N.M.P.M.	7. Unit Agreement Name 8. Farm or Lease Name <b>Holt "A" State</b> 9. Well No. <b>1</b> 10. Field and Pool, or Wildcat <b>Undesignated</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>4228' GR</b>	12. County <b>Lea</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been abandoned due to inability to establish commercial production.

11-27-70 Rigged up Dean Penick Casing Pulling Co.

1. Set cast iron bridge plug @ 9000'. Set 30' cmt plug on top of CIBP.
2. Shot off 5½" csg @ 3868'. Pulled 3868' - 5½" csg.
3. Set 40 sx cement plug 3700-3800' in 7-7/8" hole.
4. Shot off 8-5/8" csg @ 1102'. Pulled 1102' - 8-5/8" csg.
5. Set 60 sx cement plug 960'-1060' in 11½" hole.
6. Set 60 sx cement plug 310'-410' in 11½" hole & 12-3/4" csg.
7. Set 10 sx cement plug 0-15' in 12-3/4" csg.
8. Welded plate on 12-3/4" csg & set location marker.

Location ready for inspection any time after 12-15-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <i>David K. Boring</i>	TITLE <b>Division Manager</b>	DATE <b>12-11-70</b>
APPROVED BY <i>John W. Runyan</i>	TITLE <b>Geologist</b>	DATE <b>MAR 24 1971</b>
CONDITIONS OF APPROVAL, IF ANY:		

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Imperial-American Management Company</b>	8. Farm or Lease Name <b>Holt "A" State</b>
3. Address of Operator <b>507 Midland Savings Building 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>0</b> <b>1980'</b> FEET FROM THE <b>East</b> LINE AND <b>720</b> FEET FROM THE <b>South</b> LINE, SECTION <b>4</b> TOWNSHIP <b>10S</b> RANGE <b>34E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undesignated</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4228 GR</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

I. Well is to be abandoned due to inability to establish commercial production.

II. Casing is as follows:  
Surface Casing - 12-3/4" set @ 360' - cement circulated  
Intermediate Casing - 8-5/8" set @ 4069' - 500 sx cement.  
Production Casing - 5-1/2" set @ 10,000' - 350 sx cement.

III. Perforations:  
Bough "C" - 9889-92'. Cast Iron Bridge Plug set @ 9792' w/1 sx cement on top.  
Bough "A" - 9531-9636. Open

IV. Proposed Abandonment Procedure.

1. Load hole w/mud.
2. Set 25 sx cement plug - 9300-9500'.
3. Shoot off and pull 5-1/2" casing from free point.
4. Set 100' cement plug over stub.
5. Shoot off and pull 8-5/8" casing from free point.
6. Set 100' cement plug-half in, half out of 8-5/8" stub.
7. Set 100' cement plug-half in, half out of 12-3/4 (310'-410')
8. Set 10 sx plug at surface.
9. Remove wellhead. Set marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operations Superintendent DATE June 1, 1970

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT DATE JUN 4 1970

CONDITIONS OF APPROVAL, IF ANY:  
25 sxs @ Top Abo if exposed