

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 4541

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Western States Producing Company	8. Farm or Lease Name T. P. State "4"
3. Address of Operator 900 Building of the Southwest Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER 0, 660 FEET FROM THE south LINE AND 2100 FEET FROM THE east LINE, SECTION 4 TOWNSHIP 11-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Inbe (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4220' GL	12. County Lea

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 35 sks. cement plug from 9985' to 9515' in 4 1/2" casing.
- Free point and cut-off 4 1/2" casing at 7650' and spot 50 sack plug from 7650' to 7510' in 7 7/8" hole.
- Spot 35 sack plug at top of Glorieta (5480') back to 5380' in 7 7/8" hole.
- Spot 50 sack plug from 4200' to 4100' (8 5/8" set at 4150').
- Free point and cut-off 8 5/8" at 2500' and spot 50 sack plug at 2500' in 11" hole.
- Spot 75 sack plug from 410' to 310' (13 3/8" set at 360').
- Spot 10 sack plug at surface, set marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don C. Bennett TITLE Operations Manager DATE June 21, 1971  
APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT 1 DATE JUN 23 1971  
CONDITIONS OF APPROVAL, IF ANY: