					o 1971
	IES RECEIVED	<del></del>	M.	HI.	Form C-103
	IBUTION				Supersedes Old C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION					Effective 1-1-65
FILE					
U.S.G.S.		+			5a. Indicate Type of Lease
LAND OFF			-		State X Fee
OPERATOR					5. State Oil & Gas Lease No.
					L-210
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
					7. Unit Agreement Name
WELL X WELL OTHER.					None
2. Name of Operator					8, Farm or Lease Name
ROGER C. HANKS					Teresa
3. Address of Operator					9. Well No.
606 Wall Towers West, Midland, Texas 79701					1
4. Location of Well					10. Field and Pool, or Wildcat
UNIT LETTER H , 660 FEET FROM THE East LINE AND 1980 FEET FROM					BAR U PENN
THE North LINE, SECTION 11 TOWNSHIP 95 RANGE 32E NMPM.					
15. Elevation (Show whether DF, RT, GR, etc.)					12. County
16.		4426.5 GR			Lea AllIIIIII
Check Appropriate Box To Indicate Nature of Notice, Report or Other NOTICE OF INTENTION TO:					er Data
					REPORT OF:
PERFORM REM	IEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	XX	ALTERING CASING
TEMPORARILY	ABANDON		COMMENCE DRILLING OPNS.	Ē	PLUG AND ABANDONMENT
PULL OR ALTE	R CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	H	
			OTHER		
OTHER					
			l		
17. Describe   work) SEI	Proposed or Complet E RULE 1103.	ed Operations (Clearly state all pertinent det	ails, and give pertinent dates, i	including e	stimated date of starting any proposed
•		ell with hot oil.			
2-18-70 Moved on pulling unit. Pulled pump and packer and ran					an tubing open-ended
2-19-70 Pumped 9.5 bbls. production water for pad, 2,500 gal. 20% D.S. 30 NE					
	acid with	2 1/2 gal. 1-11. Spot	ted acid with 3	4 8 h	his production
acid with 2 1/2 gal. 1-11. Spotted acid with 34.8 bbls. production water. Casing and tubing on strong vacuum. Total fluid to recover					
107.5 bbls. Set for 4 hours. Started to swab. Fluid le					id lovel 75001 from
surface. Recovered water and spent acid. Good show					of and and ail
	after swa	bbing 3 hours.	Jone deru. 3000	SHOW	or yas and OIT
2-20-70 SIP 150#. Swabbed well. Fluid level 5000' from surface. Swabb					
	hours we	ll kicked off and start	rever source irol	m sur	A LO LAL
2-21-70	Well made	280 bbls. in 23 hours.	tou trowing at a	Idte	or to bors. per hr.
2-22-70	Flowing	235# tubing pressure.	17/6111	T c+ -	
	- TOWTING.	200m cubing pressure.	4//04" CNOKE.	LOts	or gas.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED Kerrer Hauks by Wauda hutter perature	DATE 3-2-70
APPROVED BY Leslie N. Clemente TITLE Oil & Gas insporter	DATE

CONDITIONS OF APPROVAL, IF ANY: