

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
NM-3806036-0

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name Hugo, 693 Ltd.	
3. Address of Operator 104 South Pecos; Midland, Texas 79701	9. Well No. 2	
4. Location of Well UNIT LETTER <u>L</u> , <u>1,980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>9-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated(San Andres)	
15. Elevation (Show whether DF, RT, GR, etc.) 4,155' GL	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 9,816' PB 5,693'  
(San Andres) Perfs. 4,818'-4,852'

Propose to P&A as follows:

POH w/rods & tbq.  
Set CIBP @ 4,700' w/20' cmt on top *CORD HOLE w/ MLK*  
Cut & pull 5-1/2" csg. - Top cmt @ 4,526' Per CBL 3-12-86  
40 sx plug @ 4,400' (5-1/2" stub) - tag  
50 sx plug @ 4,130' (8-5/8" shoe) - tag  
Cut & pull 8-5/8" csg.  
75 sx @ 8-5/8" shoe (est. 1,000') - tag  
75 sx @ 425' (12-3/4" shoe)  
10 sx @ surface & install Dry Hole Marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. D. Boyce TITLE Production Supervisor DATE 6-9-86

APPROVED BY DISTRICT I SUPERVISOR TITLE  DATE JUN 11 1986

CONDITIONS OF APPROVAL, IF ANY: