

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4726

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Present Status - Temp. Abnd.	7. Unit Agreement Name ----
2. Name of Operator Hanagan Petroleum Corporation	8. Farm or Lease Name Sawyer-State
3. Address of Operator P. O. Box 1737, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 460 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 10S RANGE 37E NMMP.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3977 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well presently temporarily abandoned with 4½" prod. csg. @ 5037', PB 5010', orig. TD 5050'. 8-5/8" surf. csg. set and cement circ. @ 364. Propose to pull and salvage approx. 1000' of 4½" csg., set 100' cement plugs as follows:

4910-5010' (inside 4½" csg.)
950-1050' (50' inside & 50' outside stub of 4½" csg.)
300- 400' (@ base of 8-5/8" surf. csg.)

10 sx. @ surf. w/appropriate dry hole marker.

Top anhydrite 2300', so all salt section behind 4½" csg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Hugh C. Hanagan</u>	TITLE <u>Vice President</u>	DATE <u>4/2/70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR</u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		