Form 9-331 (May 1963)

## UNITED STATES SUBMIT IN TRIPLICA (Other instructions verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

·	DEPARTMEN. OF THE INT					
	GEOLOGICAL SURVE	Υ		<u>NM-0558984</u>		
CHND	RY NOTICES AND REPORT	TS ON WELLS		6. IF INDIAN, ALLOT	TEE OR TRIBE NAME	
(Do not use this fo	rm for proposals to drill or to deepen or I Jse "APPLICATION FOR PERMIT" for s	plug back to a differen	t reservoir.		4 	
Ţ	Jse "APPLICATION FOR PERMIT—" for a	uch proposals.)	<del></del>	7. UNIT AGREEMENT	NAME OF THE PARTY	
OIL X GAS				4. UNIT AUREEMENT	RAME	
WELL WELL	OTHER			8. FARM OR LEASE 1	NAME	
NAME OF OPERATOR BTA Oil Producers				1	Starman 684 Ltd.	
. ADDRESS OF OPERATOR				9. WELL NO.		
	ecos, Midland, Texas	79701		1		
LOCATION OF WELL (Rep	ort location clearly and in accordance with	h any State requiremen	its.•	10. FIELD AND POOL	, OR WILDCAT	
See also space 17 below.) At surface 1980' FNL, 660' FEL of Sec. 4, T-9-S, R-35-E					Vada-Penn Ext.  11. SEC, T., R., M., OR BLK. AND SURVEY OR AREA	
				11. SEC., T., R., M., C SURVEY OR AL		
				Cog 4 T	-9-S, R-35-	
				12. COUNTY OR PAR		
PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				Lea	New Mexic	
	4193 K.I	<b>3.</b>	· · · · · · · · · · · · · · · · · · ·	Пец	INCW HEAT	
6.	Check Appropriate Box To Indica	ate Nature of Noti	ce, Report, o	r Other Data		
NO'	TICE OF INTENTION TO:	1		SEQUENT REPORT OF:	•	
	DULL OR ALTER CISING	WATER S	<b>井町小の前屋</b>	REPAIRIN	G WELL	
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE		TREATMENT	ALTERING	i	
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	SHOOTING	OR ACIDIZING	ABANDON		
REPAIR WELL	CHANGE PLANS	(Other)	Casing,	cementing &	test X	
(Other)		(No	TE: Report res	ults of multiple completion Report and Log	on on Well form.)	
	OMPLETED OPERATIONS (Clearly state all pevel is directionally drilled, give subsurface	rtinent details, and gi	ve pertinent da	ites, including estimated	date of starting any kers and zones perti-	
proposed work. If v nent to this work.) •	vell is directionally drilled, give subsurface	: locations and measur	ed and true to			
					/ 4 11 -	
11-26-69	Spudded 17½' hole at	4:00 P.M.	11-25-69	9. Set 12 3/	4" O.D.	
	33.38# surface casing at 390' with 400 s			sx 2% CC (Ce	ement circu-	
	lated). Plug down 4:			· ·		
11-27-69	After WOC 18 hrs tes	ted casing	to 600#	for 30 min.	Held O.K.	
	Drilling ahead.				•	
11-30-69	Drilled Il" hole to	4035'. Set	8 5/8"	O.D., 24#,28	3#,32# J-55	
11-30-03	casing at 4035' with	n 8:00 P.M.	11-30-69.			
	WOC.				·	
12.1-60	After WOC 18 hrs tes	ted casing	to 1000	for 30 min	. Held O.K.	
12-1-69	Now drilling ahead.					
	Now driffing discussion				1 1 2 ± ±.	
				en e		
	•					
				1 1 = =		
4						
18. I hereby certify that t	he foregoing is true and correct					
SIGNED	Million C. TITLE	Drlg. Mgr	•	DATE 12	-2-69	
(This space for Federa	ul or State office use)	12				
/ Twie space for redets		_				
APPROVED BY	PROVAL IF ANY:	' <del></del>	ACCEPTED	END DECODE		
COMPLETIONS OF ALL		•	MUDITIEU	194 H (234)	<i>≥</i> 2.05	

\*See Instructions on Reverse Side UEU

U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO