

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-23379

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG 2247

7. Lease Name or Unit Agreement Name

Lonestar AAI State

8. Well No.

1

9. Pool name or Wildcat

Eight Mile Draw, Permo Penn

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line

Section 19

Township 11S

Range 35E

NMPM Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4139.6' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOCD, Hobbs, prior to job.
2. GIH & dump 35' more cmt. on top of CIBP at 10249'.
3. Set CIBP at 9300' +/- and dump 35' cmt. on top.
4. Set 100' (25 sx mini) cmt. plug across ABO top at 7833'
5. Cut & pull 5 1/2" csg. TCMT 6650' by CBL.
6. Set 100' (25 sx mini) cmt plug across 5 1/2" stub. WOC & tag.
7. Set 100' (25 sx mini) cmt plug across Glorieta top at 5604'.
8. Set 100' (25 sx mini) cmt plug across 8 5/8" csg shoe at 4100'. WOC & tag.
9. Perforate 8 5/8" csg at 461' and set cmt retainer at 361'. Pump 100' (25 sx mini) cmt plug inside and outside 8 5/8" csg.
10. Set 10 sx surface plug & install P&A marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Rusty Klein (By: Pamela Evans)*

TITLE

Production Clerk

DATE

10/24/94

TYPE OR PRINT NAME

Rusty Klein (By: Pamela Evans)

505-748-1471  
TELEPHONE NO.

(This space for State Use)

State Signed by  
[Signature]  
[Signature]

APPROVED BY

TITLE

DATE

OCT 25 1994

18