

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator BTA Oil Producers		8. Farm or Lease Name Ray 700 Ltd.
3. Address of Operator 104 South Pecos, Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER "H", 1980 FEET FROM THE North LINE AND 510 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 9-S RANGE 35-E NMPM.		10. Field and Pool, or Wildcat Vada-Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4140 GL, 4152 KB		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

Set CIBP @ 9700' w/2 sx cmt on top
Cut & pull 5½" csg (T/C 8040')
25 sx @ 5½" stub
25 sx @ 5474' (Glorietta)
25 sx @ 4076 (8-5/8" shoe)
Cut & pull 8-5/8" csg
25 sx @ 8-5/8" stub
25 sx @ 375' (12-3/4" shoe)
10 sx @ surface
Install dry hole marker per NMOCC regulations

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. D. Ramey TITLE Production Clerk DATE 11/24/71

Orig. Signed by
Joe D. Ramey
Dist. I, Supv.

APPROVED BY _____ TITLE Production Clerk DATE DEC 3 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

1971

OIL CONSERVATION COMM.
HOLDS, H. M.