

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
None

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name None
2. Name of Operator W. B. Goode	8. Farm or Lease Name None
3. Address of Operator 6754 Ridgeview Circle, Dallas, Texas 75240	9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> , <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>510</u> FEET FROM THE <u>North</u> LINE, SECTION <u>22</u> TOWNSHIP <u>9-S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4144 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Pull tubing and remove
  - (2) Set cast iron plug between 9400-9500' w/35' cement cap
  - (3) Load hole w/0.5% salt gel, 25sx/100bbl water
  - (4) Free point cut off and pull 4 1/2" casing
  - (5) Set 100' cement plug across Glorieta BTM @ 5500'
  - (6) Set 100' cement plug in and out 8 5/8" shoe @ 4078'
  - (7) Set 100' cement plug in and out 8 5/8" stub @ 1565'
  - (8) Set 100' cement plug in and out 12 3/4" shoe @ 384'
  - (9) Set 10 sx cap in top w/marker
  - (10) Move tubular goods and surface equipment
  - (11) Break up pads and fill and level location
  - (12) Work is planned for first week in January, 1975
  - (13) New Mexico Oil Commission will be notified 24 hours in advance
- SET 100' CEMENT PLUG-IN & OUT 4 1/2" STUB

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe A. Steiner TITLE Agent DATE 12-31-74

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE DE

CONDITIONS OF APPROVAL, IF ANY: