

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Conservation Division

P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Number: 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

J. P. H. OIL PRODUCERS

3. Address and Telephone No.

P.O. Box 565, Lovington, N.M. 88260

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' F.S.L & 510' F.W.L Sec. 3, T12S, R33E.

5. Lease Designation and Serial No.

NM-0556674

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

AMERADA Fed 1

8. Well Name and No.

30-025-23505

9. API Well No.

BAGLEY PENN.

10. Field and Pool, or Exploratory Area

11. County or Parish, State

LEA, N.M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PLUG AND ABANDON AS FOLLOWS

- (1) Set BRIDGE PLUG @ 8600' & CAP WITH 50' CEMENT PLUG - TAG PLUG
(2) CUT & PULL 5,000' PLUS OR MINUS OF 4 1/2" CASING
(3) Set 100' plug in & out of 4 1/2" CASING STUB - TAG PLUG
(4) Set 100' Cement plug in & out of 8 3/8" CASING SHOE
(5) CUT & PULL 1,000' PLUS OR MINUS OF 8 3/8" CASING
(6) Set 100' plug in & out of 8 3/8" CASING STUB - TAG PLUG
(7) Set 50' plug in & out of SURFACE CASING SHOE
(8) Set 10' PX PLUG @ SURFACE
(9) PLACE 4'X4' DRY HOLE MARKER @ SURFACE
(10) LEVEL AND CLEAN LOCATION

PLACE MUD

14. I hereby certify that the foregoing is true and correct

Signed

Title

Date

(This space for Federal or State office use)

Approved by

(ORIG. SGD.) DAVID R. GLASS

Title

PETROLEUM ENGINEER

Date

FEB 11 1999

Conditions of approval, if any:

SEE ATTACHED FOR

CONDITIONS OF APPROVAL

Title 18 U.S.C. Section 1001, et seq., prohibits any person from knowingly and willfully making to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side

Well Must Be Plugged By 03-15-1999

RECEIVED

FEB 11 1999

BLM
ROOSEVELT, NM