

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23506
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	30-025-23506
7. Lease Name or Unit Agreement Name	SHERIDAN "A" 24256
8. Well No.	1
9. Pool name or Wildcat	VADA (PENN) 62100

1. Type of Well:	GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CARR WELL SERVICE, INC. 3700
3. Address of Operator	P.O. BOX 69090 ODESSA, TX 79769-9090
4. Well Location	Unit Letter C : 660 Feet From The FNL Line and 1080 Feet From The FWL Line
Section 24	Township T-9-S Range R-33-E NMPM I.E.A. County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4340'

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
CARR WELL SERVICE, INC. 3700

3. Address of Operator  
P.O. BOX 69090 ODESSA, TX 79769-9090

4. Well Location  
Unit Letter C : 660 Feet From The FNL Line and 1080 Feet From The FWL Line

Section 24 Township T-9-S Range R-33-E NMPM I.E.A. County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4340'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 100' CMT PLUG FROM 9600'-9500' TAG OR CIBP W/35' CMT @9600'
- 100' CMT PLUG 50' IN & 50' OUT 5-1/2 CSG STUB. TAG (5500'+-)
- 100' CMT PLUG 50' BELOW & 50' ABOVE 8-5/8 SHOE (SHOE @3950') TAG
- PERF. 8-5/8 CSG. @1930' (SALT) 100 CMT PLUG INSIDE & OUTSIDE 8-5/8 CSG.
- 100' CMT PLUG 50' IN & 50' OUT 8-5/8 CSG STUB. TAG.
- 100' CMT PLUG BELOW & 50' ABOVE 13-3/8 CSG SHOE (SHOE @397') TAG.
- 10 SX SURF. PLUG
- INSTALL DRY HOLE MARKER.

NOTE: HOLE CIRCULATED W/10# BRINE W/25# SALT GEL PER BBL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlie A. Spann TITLE Supervisor DATE 2/20/90

TYPE OR PRINT NAME Charlie A. Spann TELEPHONE NO. 915/362-4324

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE SEP 22 '92

CONDITIONS OF APPROVAL, IF ANY:

R A

8