

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved:
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 069300

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Mobil Atlantic Fed.

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Allison Penn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10, T-9-S, R-36-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BLACKROCK OIL COMPANY

3. ADDRESS OF OPERATOR

1000 V & J Tower, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit B, 660 FNL & 1980 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GH, etc.)

4089' G. L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☒ALTERING CASING ☐ABANDONMENT* ☐Set Whipstock ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTE: April 9, 1971, the 4-1/2" casing collapsed at 6146', subsequent attempts to repair were unsuccessful. The casing above this point was pulled.

7-1-71

- 1.) Spot 250 sx cement plug @ 6235', tag plug, no plug. Spot second 250 sx plug. Tag plug. 50' of fill - spot 500 sx cement plug, plugged back to 5833'.
- 2.) Dress cement to 5849'. Run whipstock at 5849', kick off hole 3-3/4° @ 5900', 4° @ 5969', 2-3/4° @ 6189', and 2-1/2° @ 6264'.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

July 14, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD
AUG 18 1971
U. S. GEOLOGICAL SURVEY,
HOBBS, NEW MEXICO

RECEIVED

AUG 2 1974

OIL CONSERVATION COMM.
HOUSTON, TEX.