

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-4-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Oil Development Company of Texas	8. Farm or Lease Name SFPRR
3. Address of Operator 900 Polk Street, Amarillo, Texas 79101	9. Well No. 11
4. Location of Well UNIT LETTER <u>L</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>860</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>9S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat West Sawyer (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 3973' Gr 3984' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is our intention to work this well over (beginning 11-14-72) as follows:

1. Pull rods and pump.
2. Squeeze perfs 4928-56', 69'- 78', 81-93 w/200 sx.
3. Drill out and reperf San Andres 4997', 96', 87', 86', 77', 74', 71', 70', 47', 46', 45', 44' (12 holes).
4. Reacidize 7,650 gals 15% NE.
5. Run tubing and pump; put back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief,

SIGNED D. T. Stogner TITLE Petroleum Engineer DATE November 10, 1972

APPROVED BY John Runyan TITLE Geologist DATE NOV 13 1972
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 13 1972

OIL CONSERVATION COMM.
HOBBS, N. M.